

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	es Present During the Inspection:
Company	Rusty Netz
OGM	Karl Houskeeper

Inspection Report

Permit Number:	C0070035
Inspection Type:	PARTIAL
Inspection Date:	Thursday, February 17, 2011
Start Date/Time:	2/17/2011 8:00:00 AM
End Date/Time:	2/17/2011 11:00:00 AM
Last Inspection:	Thursday, January 20, 2011

Inspector: Karl Houskeeper, Weather: Clear, Temp. 35 Deg. F.

InspectionID Report Number: 2651

Accepted by: jhelfric

3/3/2011

Permitee: SUNNYSIDE COGENERATION ASSOCIATES Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	310.00
Total Disturbed	202.00
Phase I	5.50
Phase II	
Phase III	

Mineral	Ownership
---------	-----------

Underground

_	•	•	_	_	٠
7	•	٠.	_		
_	- 3	it.	ш	Œ	,

Соц	nt

	Surfac
_	

County

Loadou

Y	Fee
	Other

	Processing
J	Panrocossino

Types of Operations

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl R. Hawbuper

Date

Thursday, Febr



Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Thursday, February 17, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	~		Y	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓	✓		
6.	Disposal of Excess Spoil, Fills, Benches	V			
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓			
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Thursday, February 17, 2011

Page 3 of 3

2. Signs and Markers

The mine identification sign is located at the entrance into the permit area. The sign contained the required information.

4.a Hydrologic Balance: Diversions

Tumble weeds were found in several diversions against the inlets and outlets of culverts. The weeds need to be removed. One culvert inlet was observed to be one third to one half full of sediment. The referenced inlet in at the road entrance to the Star Point Fuel Pile Storage entrance.